

Summary of Study Report in Pictures:

ECO-TOURISM SCHEME

S. n.	Village	Name of Activity	Latti tude	Longi tude	Overall quality	Observations	Recommendation	Photo of observe work/structure
1	Manu devi	Solar and Submersible pump purchase	N- 21.285 814	E- 75.565 128	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
2	Manu devi	Purchasing of Solar Streets & Home Lights	N- 21.285 965	E- 75.565 020	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
3	Manu devi	Erection of Bore well For Drinking Water	N- 21.285 723	E- 75.565 258	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
4	Manu devi	Cement Bandhara Construction -03	N- 21.29 6338	E- 75.563 718	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
5	Manu devi	Beatification of Van Udyan	N- 21.28 3345	E- 75.565 128	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
6	Manu devi	Shrub Plantation In Van Udyan	N- 21.285 723	E- 75.565 258	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
7	Manu devi	Sintex Tank & Water Platform Pipeline -147	N- 21.17 8446	E- 75.335 4.17	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
8	Manu devi	Chain Link Fencing & Entry Gate (ON 1477)	N- 21.170 0.83	E- 75.335 7.81	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
9	Manu devi	Sintex Tank Water Platform Pipeline -147	N- 21.170 9.66	E-75.33 53.94	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
10	Manu devi	Shobhivanti Zadezudape Lomp. No. 147	N- 21.17 08.18	E-75.33 54.38	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
11	Manu devi	Shobhivanti Zadezudape (Hedge). No. 147	N- 21.170 8.18	E- 75.335 4.38	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	



12	Manu devi	Hirvalicha Galicha-Com.No-147	N-21.170 9.56	E-75.33 54.68	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
13	Manu devi	Construction of Niwara In Comptt-No-147	N-21.170 9.58	E-75.33 54.68	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
14	Manu devi	Flower Bed And Shrub Plantation	N-21.17 08.18	E-75.33 5438	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
15	Manu devi	Chain-link fencing for protection Adegaon garden	N-21.17 08.18	E-75.33 5438	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
16	Manu devi	Lawn in Vanvihar Spot Compt no. -147	N-21.170 8.18	E-75.33 5438	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
17	Mor dharan	Creation of Green bed Lawn & Plantation	N-21.15 2116	E-75.49 1250	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
18	Mor dharan	Sintex Tank & Water Platform Pipeline -77	N-21.15 2371	E-75.47 5760	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
19	Mor dharan	Erection of Lokhandi Nirikshan Stand	N-21.15 2372	E-75.47 5761	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
20	Mor dharan	Hedge Plantation on both side at Nakshtra van	N-21.15 21.18	E-75.47 6490	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
21	Mor dharan	Plantation of shrub hedge steps in C no. 77	N-21.15 2091	E-75.47 6294	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
22	Mor dharan	Paver Block Placement	N-21.15 2170	E-75.47 5871	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
23	Mor dharan	Cement Bandhara at charmali no. 83-03	N-21.15 2142	E-76.47 6390	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

























24	Mor dharan	Plantation of Shrub Hedge steps at no. 77	N-75.21 2221	E-21.15 2222	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
25	Mor dharan	Herbal Garden Plantation in Rest house area	N-21.16 2223	E-75.47 5741	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
26	Rajvad	Pagoda	Nil	Nil	Nil	Not Started Yet	Nil	Nil
27	Rajvad	RCC Watch Tower	Nil	Nil	Nil	Not Started Yet	Nil	Nil
28	Rajvad	Shrub Plantation	Nil	Nil	Nil	Not Started Yet	Nil	Nil
29	Rajvad	Lawn Bed	Nil	Nil	Nil	Not Started Yet	Nil	Nil
30	Rajvad	Flower Bed	Nil	Nil	Nil	Not Started Yet	Nil	Nil
31	Rajvad	Kamal Kund	Nil	Nil	Nil	Not Started Yet	Nil	Nil
32	Padma laya	Board In Van Chetana Kendra	N-31.00 9943	E-75.56 1135	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
33	Padma laya	Natural Trail	N-31.00 99448	E-75.56 1140	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
34	Padma laya	Water Supply	N-31.00 9950	E-75.56 1144	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
35	Padma laya	Chain-link Fencing	N-31.00 9953	E-75.56 1145	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

36	Padma laya	Cement Dam	N- 31.00 9954	E- 75.56 1147	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
37	Padma laya	Shrub Plantation	N- 31.00 9958	E- 75.56 1149	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
38	Padma laya	Enterace Gate of Lawn	N- 31.00 9960	E- 75.56 1150	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
39	Padma laya	Cement Dam	N- 31.00 9962	E- 75.56 1152	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
40	Padma laya	Flower Bed	N- 31.00 9964	E- 75.56 1154	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
41	Padma laya	Fencing Garden Right Side	N- 31.00 9966	E- 75.56 1157	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
42	Padma laya	Fencing Rest House	N- 31.00 9963	E- 75.56 1158	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
43	Padma laya	Cement Dam	N- 31.00 9968	E- 75.56 1162	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
44	Padma laya	Fencing Garden Left Side	N- 31.00 9970	E- 75.56 1164	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
45	Padma laya	Fencing towards Bhim Kund	N- 31.00 9972	E- 75.56 1166	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
46	Padma laya	Fencing Garden Side	N- 31.00 9974	E- 75.56 1170	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
47	Padma laya	Fencing Nature Trail Right Side	N- 31.00 9976	E- 75.56 1172	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

48	Padma laya	Fencing Nature Trail Left Side	N- 31.00 9980	E- 75.56 1173	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
49	Padma laya	Garden Equipment	N- 31.00 9910	E- 75.56 1174	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
50	Waghara	Pagoda- 1	N- 20.48 4050	E-075.9 1710	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
51	Waghara	Van bandhara	N- 20.48 1952	E-075.9 3211	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
52	Waghara	Well Digging	N- 20.48 4053	E-075.9 1713	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
53	Waghara	Nature Trail	N- 20.48 4054	E-075.9 1714	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
54	Waghara	Gully Plugging	N- 20.48 4055	E-075.9 1716	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
55	Waghara	Garden Equipment	N- 20.48 4056	E-075.9 1717	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
56	Waghara	Paver Block	N- 20.48 4557	E-075.9 15.18	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
57	Waghara	Pagoda	N- 20.48 4558	E-075.9 1519	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
58	Waghara	Cement Bench	N- 20.48 4559	E-75.91 1520	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
59	Waghara	Watch Tower	N- 20.48 4560	E-75.91 15.22	Satisfa ctory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	



60	Waghara	Cement Dam-1	N-20.48 45.61	E-75.91 15.23	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
61	Waghara	Cement Dam-2	N-20.48 45.62	E-75.91 15.24	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
62	Waghara	Cement Dam-4	N-20.48 45.63	E-75.91 15.25	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
63	Waghara	W.C. and Toilet	N-20.48 45.64	E-75.91 15.27	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
64	Waghara	Gully Plugging	N-20.48 45.65	E-75.91 1528	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
65	Waghara	Gal Kadhane /MVD	N-20.48 45.66	E-75.91 1529	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
66	Waghara	Fence Nursery	N-20.48 45.67	E-75.91 1530	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
67	Waghara	Cement Dam -3	N-20.48 45.68	E-75.91 1531	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
68	Waghara	Nakshatra Van	N-20.48 45.69	E-75.91 1532	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
69	Waghara	Garden Equipment	N-20.48 45.70	E-75.91 1533	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
70	Waghara	Fencing East Of Nursery	N-20.48 45.71	E-75.91 1534	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
71	Waghara	Chain Link Fencing In front of Pagoda	N-20.48 45.72	E-75.91 1535	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

72	Waghara	Fruit Plants Plantation	N-20.48 45.73	E-75.91 1536	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
73	Waghara	Panchawati Van	N-20.48 45.74	E-75.91 1537	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
74	Waghara	Fencing With Gate	N-20.48 45.75	E-75.91 1538	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
75	Waghara	Fencing East Of temple	N-20.48 45.76	E-75.91 1539	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
76	Waghara	Foot Bridge	N-20.48 45.77	E-75.91 1540	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
77	Waghara	Fencing Back Of Nursery	N-20.48 45.78	E-75.91 1541	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
78	Pahan	Chain Link Fencing	N-20.43 3245	E-75.27 2328	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
79	Unap dev	Hedge Plantation near Public Hall area	N-21.00 7658	E-75.56 26.04	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
80	Unap dev	Rose Garden Near Rest house & roadside	N-21.00 7659	E-75.56 26.07	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
81	Unap dev	Landscaping Of Herbal & Medicine Plantation	N-21.00 7660	E-75.56 26.09	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
82	Unap dev	Sprinkler & Drip set For Rose Garden	N-21.00 7661	E-75.56 26.10	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
83	Unap dev	Hedge Plantation & Lawn Pagoda Railway Station	N-21.00 7662	E-75.56 26.13	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	



84	Unap dev	Purchasing of Water Cooler & Water Purifier	N-21.00 7663	E-75.56 26.16	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
85	Unap dev	Heavy duty Clearing saw Grass Cutter Machine	N-21.00 7664	E-75.56 26.18	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
86	Unap dev	Garden Near Pond	N-21.00 7665	E-75.56 26.20	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
87	Unap dev	Hedge Plantation with Paver Block	N-21.00 7666	E-75.56 26.22	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
88	Unap dev	Lawn on Slope at rushi gumfa	N-21.00 7667	E-75.56 26.22	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
89	Unap dev	Green Lawn Under tree Shed at no. 197	N-21.00 7668	E-75.56 26.24	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
90	Unap dev	Green Lawn and Hedge Plantation-part2	N-21.00 7669	E-75.56 26.26	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
91	Unap dev	Green Lawn Flower Bed Garden	N-21.00 7670	E-75.56 26.28	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
92	Unap dev	Drain Removal Of Excess Water In Kund	N-21.00 7671	E-75.56 26.29	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
93	Unap dev	Sprinkler & Drip set For Van Udyan at Unapdeo	N-21.00 7672	E-75.56 26.30	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
94	Maha deo Mal	Plantation SYO (540/2000)	N-20.55 06.53	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
95	Maha deo Mal	Garden Equipment	N-20.55 06.52	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

96	Maha deo Mal	Tall Plantation	N-20.55 06.51	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
97	Maha deo Mal	Irrigated Plantation 2000 Plants	N-20.55 3624	E-76.02 8404	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
98	Maha deo Mal	Nisarg Nirvachan Kendra	N-20.55 06.57	E-76.02 36.04	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
99	Maha deo Mal	Watch Tower	N-20.55 06.56	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
100	Maha deo Mal	Protection Hut	N-20.55 06.53	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
101	Maha deo Mal	Well Digging	N-20.55 06.59	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
102	Maha deo Mal	10000 Liter Water Tank And Pipeline	N-20.55 06.58	E-75.47.4 4.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
103	Maha deo Mal	Chain Link Fencing	N-20.55 06.57	E-75.47 44.00	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
104	Maha deo Mal	Pagoda-4	N-20.55 06.57	E-75.47.4 4.49	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
105	Male gaon	Plantation SYP (540/2000 Plants)	N-20.57 3628	E-76.02 08.42	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
106	Male gaon	Pipe Line	N-20.57.1 9.48	E-76.02 05.09	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
107	Male gaon	Garden Maintenance	N-20.57 1948	E-76.02 05.11	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

108	Male gaon	Landscaping	N-20.57 19.48	E-76.02 5.099	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
109	Male gaon	Digging Well and construction	N-20.57 3508	E-76.02 06.14	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
110	Male gaon	Protection Wall	N-20.57.3 502	E-76.02 06.13	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
111	Male gaon	Chain-link Fencing 200 RMT	N-20.57.3 5.09	E-76.02 09.61	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
112	Male gaon	Chain-link Fencing	N-20.57.3 5.10	E-76.02 06.62	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
113	Male gaon	Nature Trail	N-20.57 35.08	E-76.02 06.64	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
114	Male gaon	Water Tank and Pipe Line	N-20.57 35.09	E-76.02 06.04	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
115	Male gaon	Forest Park	N-20.57 3508	E-76.02 6104	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
116	Male gaon	Ladies Toilet	N-20.57 3505	E-76.02 06.12	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
117	Male gaon	Irrigated Plantation of 2000 plants	N-20.57.3 507	E-76.02 06.14	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
118	Male gaon	Garden Equipment	N-20.57 3508	E-76.02 20.61	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
119	Male gaon	Tall Plantation	N-20.57 3505	E-76.02.0 616	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

120	Malegaon	Chain Link Fencing	N-20.57.3504	E-76.020617	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
121	Charthana	Water Park	N-21.6367.93	E-76.1454.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
122	Charthana	Ladies Toilet	N-21.6367.94	E-76.1454.93	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
123	Charthana	Pedal Boat-2	N-21.6367.95	E-76.1454.94	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
124	Charthana	Jacket	N-21.6367.96	E-76.1454.95	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
125	Charthana	Paver Block and Steps	N-21.6367.97	E-76.1454.96	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
126	Charthana	Lawn	N-21.6367.98	E-76.1454.97	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
127	Charthana	Inspection Hut - New	N-21.6367.99	E-76.1454.98	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
128	Charthana	Coffee Tea Machine	N-21.6367.92	E-76.1454.99	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
129	Charthana	Zorbing Ball -2	N-21.6367.93	E-76.1454.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
130	Charthana	Board in Van Chetana Kendra-15	N-21.6367.94	E-76.1454.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
131	Charthana	Board in Van Chetana Kendra-17	N-21.6317.90	E-76.1454.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	



132	Char thana	Water Platform	N-21.03 67.89	E-76.14 54.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
133	Char thana	Material for Nirikshan Kuti	N-21.03 67.90	E-76.14 54.91	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
134	Char thana	Irrigated Plantation 600 Plants	N-21.03 67.90	E-76.14 54.91	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
135	Char thana	Gents Toilet	N-21.03 67.90	E-76.14 54.91	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
136	Char thana	Tall plantation-600	N-21.03 67.91	E-76.14 54.92	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
137	Char thana	Pop Corn Machine- 1	N-21.03 67.93	E-76.14 54.94	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
138	Char thana	Security Guard Cabin	N-21.03 67.94	E-76.14 54.95	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
139	Har tala	Garden Equipment (2406/3622)	N-21.00 7658	E-75.56	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
140	Har tala	Bird Watching Ota (2406/3622)	N-21.03 67.96	E-76.14 54.97	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
141	Har tala	Tall Plantation (2406/3622)	N-21.03 67.97	E-76.14 54.98	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
142	Har tala	Maintenance of Forest Park	N-21.01 60.75	E-76.02.9 064	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
143	Har tala	Plantation SYO (540/2000 Plants)	N-21.00 5851	E-76.01 7572	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

144	Har tala	Van Chetana Kendra	N-21.01 60.75	E-76.02.9 064	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
145	Har tala	Beautification in Forest Park	N-21.01 06.76	E-76.02.9 064	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
146	Har tala	Chain-link Fencing (2406/3622)	N-21.01 06.75	E-76.02.9 065	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
147	Har tala	Well Digging (2406/3622)	N-21.01 07.02	E-76.02.8 459	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
148	Har tala	Chain-link Fencing (2406/3622)	N-21.00 5851	E-76.01 7572	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
149	Har tala	Irrigated Plantation 2000 Plants (2406/3622)	N-21.00 6231	E-76.01 7242	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
150	Har tala	Ladies/Gents Toilet (2406/3622)	N-21.00 6232	E-76.01 7243	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
151	Sevoga	Water Platform	N-20.40 9071	E-75.56 35.58	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
152	Sevoga	Tall Plantation	N-20.40 9072	E-07.55 06.35	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
153	Sevoga	Natura Trail	N-20.40 9073	E-07.55 06.36	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
154	Sevoga	Well Digging	N-20.40 9074	E-07.55 06.37	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
155	Sevoga	Irrigated Plantation 2000 plants	N-20.40 9075	E-07.55 06.38	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

156	Sevoga	Ladies / Gents toilet	N-20.40 9076	E-07.55 06.39	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
157	Sevoga	Wild Life Toys & Solar Light	N-20.40 9077	E-07.55 06.40	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
158	Sevoga	Nakshatra Van	N-20.40 9078	E-07.55 06.41	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
159	Sevoga	Gully Plugging	N-20.40 9079	E-07.55 06.42	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
160	Sevoga	Chain Link Fencing	N-20.40 9080	E-07.55 06.43	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
161	Pal	Shrub Plantation In Step Garden at Anupam Rest	N-21.36 1532	E-15.90 1319	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
162	Pal	Retaining Wall in front of Anupam Rest House	N-21.34 1532	E-15.90 1320	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
163	Pal	Ladies and Gents Toilet construction	N-21.36 1532	E-15.90 1321	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
164	Pal	Construction of Paver Block at Anjan Rest House	N-21.36 1533	E-15.90 1322	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
165	Pal	Nirikshan Manora construction at no. 57	N-21.36 1534	E-15.90 1323	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
166	Pal	Path Way In Camp No 288 Pal, Park	N-21.36 1535	E-15.90 1324	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
167	Pal	Sprinkler & Drip Irrigation near canteen area	N-21.36 1537	E-15.90 1325	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	



168	Pal	Beautification near canteen and Niwara	N-21.36 1539	E-15.90 1326	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
169	Pal	Main Gate to Anupuram Rest Natural Pedestrian	N-21.36 1540	E-15.90 1327	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
170	Pal	Sprinkler & Drip system in rest house area	N-21.36 1542	E-15.90 1328	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
171	Pal	Chain Link Fencing Near Water Tank	N-21.36 1544	E-15.90 1329	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
172	Pal	Construction of Kitchen in Anupam Gest house.	N-21.36 1546	E-15.90 1335	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
173	Pal	Repairing of the Hanging Bridge.	N-21.36 1548	E-15.90 1337	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
174	Pal	Drinking Water Facility for Tourist - 03	N-21.36 1550	E-15.90 1338	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
175	Pal	Heavy Duty Cleaning Saw Grass Cutter	N-21.36 1552	E-15.90 1340	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
176	Pal	Display Board of wild animals & Protection	N-21.36 1554	E-15.90 1344	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
177	Pal	Purchas of Molded Chairs for Nirvachan Kendra.	N-21.36 1556	E-15.90 1348	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
178	Pal	Chain Link fencing near WC Unit of Baniya tree	N-21.36 1557	E-15.90 1350	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
179	Pal	Chain Link fencing near Anjan Rest house.	N-21.36 1548	E-15.90 1352	Satisfactory	* Poor Maintenance & Documentation * No Display Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	

180	Pal	UCR Masonry Wall with railing	N-21.36 1549	E-15.90 1356	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
181	Pal	Net Shed Udyan Construction	N-21.36 1550	E-15.90 1357	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
182	Landorkhori	Board in Van Chetna Kendra	N-20.97 5011	E-75.55 3867	Satisfactory	* Poor Maintenance & Documentation	* Documents Updation *Regular Maintenance	
183	Landorkhori	Road Side Plantation	N-20.97 5012	E-75.55 3869	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
184	Landorkhori	Construction of Water Tank & Water Supply	N-20.97 5013	E-75.55 3870	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
185	Landorkhori	Water Supply	N-20.97 5014	E-75.55 3874	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
186	Landorkhori	Road Side Plantation	N-20.97 5015	E-75.55 3871	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
187	Landorkhori	Hedge Plantation	N-20.97 5016	E-75.55 3872	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
188	Landorkhori	Lawn & Flower Bed	N-20.97 5017	E-75.55 3873	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
189	Landorkhori	Road Side Plantation TYO	N-20.97 5018	E-75.55 3874	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	
190	Kumbharkhori	Chain-link Fencing	N-20.97 5019	E-75.55 3876	Satisfactory	* Poor Maintenance & Documentation * No Disply Board iemwise	* Provision for Display Board * Documents Updation *Regular Maintenance	